ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra
Street ID	**Street Name**	**Significant Landmark**
W0601	NA	Dasarahalli
Segment No.	**Total Length (m)**	
6/S-W0601/S055424	214.32	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	214.32	77.611566	13.058705	77.611422	13.056815	Dasarahalli main road	dead end

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads and drains of Ambedkar colony main road Dasarahalli in ward no. 6 Byatarayanapura sub division.	4000000	2015-16
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Others	RCC drain
Tender	**Work Details**	**Job No. / Work Code**
Tender		006-15-000026
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/21 /2016-17	30/04/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
27/10/2018	27/10/2019	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
V.Chandrappa		0.00
Phone No.	**E-Mail ID**	
9448447181		

Field Inspection Details

Number of Trees

0

Any Other Information

Name

daramsingh

Date of Inspection

13/11/2018

Remarks

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark